



Georgia Analyzer System Message

Georgia's Clean Air Force (GCAF)

August 7, 2008

Message: 39000 Analyzers: 1037

Restraint Rollers for Dynamometers

Stations equipped with dynamometers are **required** to have functional restraint rollers. Stations not meeting this requirement will **fail** the audit and will be required to schedule another audit once the proper restraint rollers are in place.

800.449.2471

info@cleanairforce.com

CleanAirForce.com

Contact your equipment manufacturer (EM) today if your dynamometer does not have the required functional restraint rollers.

EM Contacts

ESP Service	800.695.4377	Sales 888.377.7971
SPX Service	800.833.3377	Sales 800.233.7055
Sun/Snap-On Service	800.225.5786	
Worldwide Service	877.832.7664	Sales 800.832.7664

For more information contact GCAF Station Assistance at 800.449.2471, option 2.

If you would like to receive an e-mail copy of GAS messages or to be added to our quarterly e-newsletter, *RepairWatch* E-News, please send a request to info@cleanairforce.com.

~ GCAF recommends printing all GAS messages for your files and posting them in a prominent location for your employees to read. To retrieve or print a previous GAS message, go to the GAS message retrieval function in your analyzer and select the appropriate message to print (the analyzer holds up to 500 messages). ~