



Reminder on Highest Failed Audit Task February 26, 2019

The highest failed audit task among all limited audits was failure to pass all dynamometer calibrations. In an effort to avoid this type of failure, it is recommended that stations promptly contact their service providers to have their dynamometer serviced/repaired. If a station wishes to discontinue use of their dynamometer and continue business as a 1996 and Newer station, please submit a Station Information Update Form at <http://www.cleanairforce.com/station-information-update-instructions/> or submit a Station Update Request via the GCAF dashboard at www.gcafdashboard.com.

If you have any questions, contact GCAF Station Assistance at 1.800.449.2471, option #2, via email at industry@cleanairforce.com, or via live chat, which is available at www.cleanairforce.com.

Connect with Georgia's Clean Air Force on Facebook by visiting <https://www.facebook.com/GeorgiasCleanAirForce>, follow us on Twitter at <https://twitter.com/GACleanAirForce>, or subscribe to our YouTube channel at www.cleanairforce.com/youtube.

If you would like to receive an email copy of GAS messages or to be added to our quarterly e-newsletter, *RepairWatch* E-News, please send a request to info@cleanairforce.com.

~ GCAF and EPD require that you print, read, and store all GAS messages in a binder on or near the analyzer. GCAF and EPD also recommend that you print a second copy of these messages and post them in a prominent location for your employees to read. To retrieve and print a previous GAS message, go to the GAS message retrieval function in your analyzer and select the appropriate message to print (the analyzer holds up to 500 messages). ~